


St. George Oceanfront Cleanup



St. George Oceanfront Cleanup

- Cleanup to be conducted per Corrective Action Plan (CAP) finalized February 2004
- Estimated 11,200 cubic yards contaminated soil
- TPA Site 1 Former Diesel Tank Farm
- TPA Site 2 Former Drum Storage Area
- TPA Site 3 Inactive Gas Station
- TPA Site 25-1 Port Fuel Supply Line E-W




Figure

2

Oceanfront Sites Overview

Source: Aero Map U.S. 9/28/96
Aerial Photograph; Pribilof Project Database
Note: Approximate Locations of Supply Lines




Figure

5

Oceanfront Sites (Polarconsult 1997 UST Decommissioning)

Source: Aero Map U.S. 9/28/96
Aerial Photograph; Pribilof Project
Database; Polarconsult 1997 St.
George Debris Cleanup & UST
Decommissioning Report






Figure

3

Oceanfront Sites (Woodward Clyde Characterization)

Source: Aero Map U.S. 9/28/96
Aerial Photograph; Pribilof Project
Database




Figure

4

Oceanfront Sites (Hart Crowser Characterization)


Source: Aero Map U.S. 9/28/96
Aerial Photograph; Pribilof Project
Database



Figure

Oceanfront Sites (Tetra Tech EM Inc. Characterization)

Source: Aero Map U.S. 9/28/96
Aerial Photograph; Pribilof Project
Database




Figure

3

**Corrective Action SOW
Oceanfront Sites
St. George Island, Alaska**

Source: Aereo Map U.S. 9/28/96
Aerial Photograph; Pribilof Project
Database



55' 0 55' 110'

APPROXIMATE SCALE IN FEET
VERTICLE EXAGGERATION = 10X

FIGURE 5-4

GEOLOGIC CROSS-SECTION B-B'

ST. GEORGE ISLAND, ALASKA

TETRA TECH FM INC




FIGURE 5-5

GEOLOGIC CROSS-SECTION C-C'

ST. GEORGE ISLAND, ALASKA

TETRA TECH, INC.



Figure

2

St. George Closed Landfill
TPA Site 4/NOAA Site 4
St. George Island, Alaska

Source: CE2 Engineers CAD Drawing;
Pribilof Project Database

